


PROPOSED REHABILITATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

Sheet No.	Content
01/17	Site location
02/17	Site Anaylsis
03/17	Master Plan
04/17	Site Photos
05/17	Spectators stand
06/17	Boundary wall
07/17	Internal Elevation
08/17	3D Projection 01
09/17	3D Projection 02
10/17	3D Projection 03
11/17	3D Projection 04
12/17	3D Projection 05
13/17	3D Projection 06
14/17	3D Projection 07
15/17	3D Projection 08
16/17	3D Projection 09
17/17	3D Projection 10

AUGUST 2018
DRAWING INDEX





- 1. All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the $international\ standards\ codes\ protection.$
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

Ι.			
	No:	Date:	Description:
			REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:





THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

SITE LOCATION


AS SHOWN SCALE: AUGUST 2018

DRAWN BY:

ENG. Duale Salah REVIEWED BY:

ENG. David Wanja

Sheet No.



- 1. All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other, the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
			REVISION





International Organization for Migration (IOM)

The UN Migration Agency

Client:





THE FEDERAL REPUBLIC
OF SOMALIA

REPUBLIC HIRSHABELLE STATE, IALIA BALCAD DISTRICT

niert Title:

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

awing Title

<u>SITE ANALYSIS</u>

SCALE: AS SHOWN


DATE: AUGUST 2018

DRAWN BY:

REVIEWED BY: ENG. David Wanja

ENG. Duale Salah

Sheet No. 02/16



- 1. All dimensions are to be checked on site.Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
			REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency





THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

MASTER PLAN

AS SHOWN SCALE: DATE: AUGUST 2018

DRAWN BY:

ENG. Duale Salah REVIEWED BY:

ENG. David Wanja

Sheet No. 03/16



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

No:	Date:	Description:			
REVISION					

Implemented by:



International Organization for Migration (IOM) The UN Migration Agency

Client:





THE FEDERAL REPUBLIC OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

SITE PHOTOS


AS SHOWN SCALE: DATE: AUGUST 2018


DRAWN BY:

ENG. Duale Salah REVIEWED BY:

ENG. David Wanja


Sheet No.





SPECTATOR STAND 1

painted to Architect's approval




Notes

- 1. All dimensions are to be checked on site.Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

		No:	Date:	Description:		
)				REVISION		






DETERMINED ON SITE MINIMUM 1000MM DEEP

Notes

- 1. All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
			REVISION





- 1. All dimensions are to be checked on site.Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:	
REVISION				

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency





THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

INTERNAL


AS SHOWN SCALE: DATE: AUGUST 2018

DRAWN BY:

ENG. Duale Salah REVIEWED BY:

ENG. David Wanja

Sheet No. 07/17



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
		•	REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:



THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

<u>3D 01</u>


AS SHOWN SCALE: DATE: AUGUST 2018

DRAWN BY:

ENG. Duale Salah REVIEWED BY:

Sheet No.

ENG. David Wanja



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
			REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:



THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

3D 02

AS SHOWN SCALE: DATE: AUGUST 2018

DRAWN BY:

ENG. Duale Salah REVIEWED BY:

ENG. David Wanja

Sheet No.



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
١			
l		•	REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:



THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

oject Title:

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

Drawing Tit

<u>3D 31</u>

SCALE: AS SHOWN

DATE: AUGUST 2018

DRAWN BY:

REVIEWED BY:

ENG. Duale Salah
ENG. David Wanja

Sheet No.

10/17

<u>A:</u>



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
4444			REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:





THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

ect Title:

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

awing Title

<u>3D 04</u>

SCALE: AS SHOWN

DATE: AUGUST 2018

DRAWN BY:


REVIEWED BY:

ENG. Duale Salah
ENG. David Wanja

Sheet No

11/17

<u>A3</u>



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

No:	Date:	Description:
		REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:



THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

oject Title:

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

Drawing Tit

<u>3D 05</u>

SCALE: AS SHOWN

DATE: AUGUST 2018

DRAWN BY:


RAWN BY: ENG. Duale Salah

REVIEWED BY:

ENG. David Wanja

Sheet No.

12/17



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
ı			
ı			
ı		•	REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:



THE FEDERAL REPUBLIC
OF SOMALIA



HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

<u>3D 06</u>

AS SHOWN SCALE:

DATE: AUGUST 2018

DRAWN BY:

ENG. Duale Salah REVIEWED BY: ENG. David Wanja

Sheet No.



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:
			REVISION

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency



THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

<u>3D 07</u>


AS SHOWN DATE: AUGUST 2018

DRAWN BY:

REVIEWED BY:

ENG. Duale Salah ENG. David Wanja

Sheet No.



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- 3. The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

No:	Date:	Description:		
REVISION				

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:





THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

oject Title:
PROPOSED REHABILIATION OF
FOOTBALL STADIUM IN BALCAD
DISTRICT, MIDDLE SHABELLE REGION

rawing Title:

<u>3D 08</u>

SCALE: AS SHOWN

DATE: AUGUST 2018


DRAWN BY:

RAWN BY: ENG. Duale Salah

REVIEWED BY:

ENG. David Wanja

Sheet No. 15/17



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

No:	Date:	Description:	
REVISION			

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:



THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

oiect Title:

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

Drawing Tit

<u>3D 09</u>

SCALE: AS SHOWN

DATE: AUGUST 2018


DRAWN BY:

REVIEWED BY:

ENG. Duale Salah
ENG. David Wanja

Sheet No.

16/17



- All dimensions are to be checked on site. Any discrepancy indimensions is to be reported to the architect before anywork commence. The Architect's drawings and specifications over rule any other. the Structural Engineers detail drawings.
- 2. All construction work to comply with the international standards codes protection.
- The PV denotes permanent ventilation and must be provided above alldoors and windows where indicated.
- 4. All walls less than 200mm thick are to be reinforced with hoop iron sheet every alternate course.
- 5. All reinforced concrete works to be done according to structural detail drawings

	No:	Date:	Description:		
İ	REVISION				

Implemented by:



International Organization for Migration (IOM)

The UN Migration Agency

Client:





THE FEDERAL REPUBLIC
OF SOMALIA

HIRSHABELLE STATE, BALCAD DISTRICT

oject Title:

PROPOSED REHABILIATION OF FOOTBALL STADIUM IN BALCAD DISTRICT, MIDDLE SHABELLE REGION

Drawing Tit

<u>3D 10</u>

ENG. Duale Salah

SCALE: AS SHOWN

DATE: AUGUST 2018

DRAWN BY:

REVIEWED BY: ENG. David Wanja

Sheet No.

17/17